

CIXI FEGO AUTO PARTS CO.LTD

ADD:No. 1277 Singer Mansion, Kaifa Avenue,

Cixi, Ningbo, Zhejiang, China

Tel:+86-574-63039098 Fax:0086-574-63039090

E-mail: fegoauto@gmail.com



Alternator Pump

 IS25-01 25CC For: LR150-434, -438 LR235-402 Rotor O.D. 49mm, w.25mm, 8spl	 IS25-02 25CC For: LR150-434,-438 LR235-402 Rotor O.D.49mm, w.25mm, 16spl	 IS25-03 25CC For: LR140-411F, -423F LR105-419F LR160-440F Rotor O.D.49mm, w.25mm, 8spl	 IS25-04 25CC For: ISUZU Rotor O.D.49mm, w.25mm, 16spl
 IS25-05 25CC For: ISUZU Rotor O.D.49mm, w.25mm, 8Spl	 IS25-06 25CC For:ISUZU Rotor : O.D.49mm, w.25mm, 8Spl	 IS30-01 30CC For: LR150-434,-438,-443 Rotor O.D.49mm, w.30mm, 8spl	 IS30-02 30CC Servicing LR150-434,-438,-443、 Rotor O.D.49mm, w.30mm, 16 spl
 IS30-03 30CC For: LR140-411F,-423F、 LR150-419F、 LR155-410F Rotor O.D.49mm, w.30mm, 8Spl	 IS30-04 30CC For ISUZU(4BA1、 4BC2) Rotot O.D.49mm, w.30mm, 8Spl	 IS30-05 30CC For: LR150-430S,-430T、 LR150-435S, LR150-435T Rotor O.D.49mm, w.30mm,8spl	 IS30-06 30CC Servicing LR150-431,-432、 LR150-438, -439 Rotor O.D.49mm, w.30mm, 8Spl
 IS39-01 50CC Servicing LR150-434,-438、 - 443、 LR235-402 Rotor O.D.52.5mm, w.39, 8spl	 IS39-02 50CC Servicing ISUZU Rotor O.D.52.5mm, w.39mm, 8spl	 IS39-03 50CC For: LR140-411F,-423F、 LR150-419F Rotor O.D.52.5mm, w.39mm, 8 spl	 IS39-04 50CC For: LR150-434,-438、 -443 Rotor O.D.52.5mm, w.39mm, 8spl

 IS39-05 50CC For: ISUZU Rotor O.D.52.5mm, w.39mm, 8spl	 IS39-06 50CC For: LR170-410,-401,-407 Rotor O.D.52.5mm, w.39mm, 8spl	 IS39-07 50CC For: LR170-418/LR170-418C Rotor O.D.52.5mm, w.39mm, 8spl	 IS39-08 50CC For: ISUZU Rotor O.D.52.5mm, w.39mm, 8Spl
 IS39-09 50CC For: ISUZU Rotor O.D.52.5mm, w.39mm, 8 splines	 IS39-10 50CC For: LR170-410,-401,-407、 407T、-412T Rotor O.D.52.5mm, w.39mm, 8 splines	 IS39-11 50CC For : LR170-406C, -406E Rotor O.D.52.5mm, w.39mm, 8spl	 IS39-12 50CC For: ISUZU Rotor O.D.52.5mm, w.39mm, 8 splines
 IS41 60CC For: LR235-503C、A5TN6279 Rotor O.D.58.8mm, w.41mm, 8 spl	 IS41-ZL 60CC For: LR250-570 Rotor O.D.58.8mm, w.41mm, 8 spl	 OP-01 For: LR170-505、505B Rotor O.D.49mm, w.25mm, 6 spl	 OP-02 For: LR170-420、-427 Rotor O.D.49mm, w.25mm, 16 spl
 OP-03 For: Rotor O.D.49mm, w.25mm, 8 spl	 OP-04 For: LR1100-502 Rotor O.D.50mm, w.31mm, 8 spl	 MIT-X01 40CC For: AD 165202、-320、-321、 A5T15684 Rotor O.D.49mm, w.28mm, 8spl	 MIT-X02 40CC For: A2T01583 Rotor O.D.49mm, w.28mm, 8 spl
 MIT-X03 40CC For: A2T27477 -32077 Rotor O.D.49mm, w.28mm, 8spl	 MIT-X04 40CC For: 4D30-40CC Rotor O.D.49mm, w.28mm, 8spl	 MIT-X05 40CC For: 大柴498 (China) Rotor O.D.49mm, w.28mm, 8spl	 MIT-Z01 60CC For: AZT723873 Rotor O.D.58.8mm, w.33mm, 8 spl

 MIT-Z02 60CC Servicing A5T70283, 37300-41012 Rotor O.D.58.8mm, w.33mm, 8spl	 MIT-Z03 60CC Servicing JFB272-3 Rotor O.D.58.8mm, w.33mm, 8Spl	 MIT-D01 130CC Servicing A4TU5586 Rotor O.D.66mm, w.33mm, 8spl	 MIT-D02 130CC Servicing K296 Rotor O.D.66mm, w.33mm, 8spl
 MIT-D03 130CC Servicing 6D15, 6D22 Rotor O.D.69mm, w.44mm, 8 splines	 MIT-ZL01 60CC For: A3T00599, A3T07483 A4A3CM499 Rotor O.D.58.8mm, w.33mm, 8 splines	 MIT-ZL02 60CC Servicing 4D33 Rotor O.D.58.8mm, w.33mm, 8 splines	 MIT-ZL03 60CC Servicing A3TN6188ZL Rotor O.D.58.8mm, w.33mm, 8 splines
 MIT-ZL04 60CC Servicing 4ZB1 /498 (China) Rotor O.D.58.8mm, w.33mm, 8 splines	 MIT-ZL05 60CC Servicing Hyundai1518 Rotor O.D.58.8mm, w.33mm, 8 splines	 MIT-ZL06 60CC Servicing Mitsubishi Rotor O.D.58.8mm, w.33mm, 8 splines	 MIT-ZL07 60CC Servicing 37300-42620 Rotor O.D.58.8mm, w.33mm, 8 splines
 MIT-ZL08 60CC For Mitsubishi Rotor O.D.58.8mm, w.33mm, 8 splines	 TRA-01 60CC Servicing Transit 江铃全顺 Rotor O.D.58.8mm, w.33mm, 8 splines	 TRA-02 60CC Servicing Transit 江铃全顺 Rotor O.D.58.8mm, w.33mm, 8 splines	 TRA-03 60CC Servicing Transit Rotor O.D.58.8mm, w.33mm, 8 splines
 TRA-04 60CC Servicing A3TN1791 Rotor O.D. 58.8mm, w. 33mm, 8 splines	 TOY-01 For 2702 -54220 -54250 Rotor O.D. 50.3mm, w. 23mm, 18 splines	 TOY-02 Servicing 8-94150-344-0 Rotor O.D. 50.3mm, w. 23mm, 18 splines	 TOY-03 For 27020-54190 Rotor O.D. 50.3mm, w. 23mm, 10 splines

 TOY-04 For Toyota Rotor O. D. 50.3mm, w. 23mm, 18 splines	 TOY-05 For 27020-1290A Rotor O. D. 50.3mm, w. 23mm, 18 splines	 TOY-06 For 27020-56180 Rotor O. D. 50.3mm, w. 23mm, 18 splines	 TOY-ZL01 For 100213-1040, -1050, - 1230, -0700, 27020-54080, 27040-54020 Rotor O. D. 44.3mm, w. 23mm, 16 spl
 TOY-ZL02 For 100213-1040, -1050, - 1230, -0700, 27020-54080, 27040-54020 Rotor O. D. 44.3mm, w. 23mm, 16 spl	 LUCAS-01 Servicing A127 24188, 24230 Rotor O. D. 57mm, w. 35mm, 18 spl	 QY-1922 For Rotor O. D. 49mm, w. 25mm, 16 splines	 QY-2822 60CC For 朝柴米油2822 Rotor O. D. 58.8mm, w. 33mm, 8 splines
 QY-TW01 60CC For Rotor O. D. 58.8mm, w. 33mm, 8 splines	 QY-VP01 For BENZ190 OE: 000 230 3165	 QY-VP02 For TOYOTA Rotor O. D. 55.6mm, w. 45mm, 10 splines	 QY-PSP01 For MR267450 (4G64江铃)
 QY-PSP02 For 06030105 (丰田4Y)	 QY-PSP03 For 5288018 (Jeep)	 QY-PSP04 For 56110-RAA-A01 (广本2.4RRA)	 QY-PSP05 For 56110-PPA-A01 (广本 2.3)
			
QY-PSP06 For G06T-32-600A (KFC)	VALVE RING NIPPLE		ROTOR VANE SET O-RING